

5)

a)

$$\text{percentage regulation} = \frac{I_f (R_e \times P_{fr} + X_e \times P_{fx})}{V_p}$$

I_f = full load current

R_e = Equivalent Resistance / winding Resistance

X_e = Equivalent Reactance / leakage Reactance

V_p = Supply Voltage

P_{fr} = Lagging power factor with regards to resistance

P_{fx} = Lagging power factor with regards to reactance

$$I_f = \frac{200,000}{415} = 481.928 \text{ to } 3.d.p$$

$$R_e = 0.014$$

$$X_e = 0.057$$

$$P_{fr} = 0.8$$

$$\text{so } \cos^{-1}(0.8) = \theta$$

$$\theta = 36.87 \text{ to } 2.d.p$$

5a)

$$\sin \theta = 0.6$$

$$P_{fr} = 0.6$$

S.

$$\text{percent regulation} = \frac{481.928 (0.014 \times 0.8 + 0.057 \times 0.6)}{415}$$

$$= \frac{481.928 (0.0112 + 0.0342)}{415}$$

$$= \frac{481.928 \times 0.0454}{415}$$

$$\frac{21.88}{415} \text{ to } 2.d.p$$

$$= 0.053 \text{ to } 3.d.p$$

$$\text{or } 5.272 \% \text{ to } 3.d.p$$

5b)

Per unit regulation

$$= I_1 (R_e \cos \phi_2 + X_e \sin \phi_2)$$

ϕ_2 = Phase angle of secondary current

R_e = equivalent resistance referred to primary

X_e = " reactance " " " "

$$R_e = R_1 + R_2 \left(\frac{V_1}{V_2} \right)^2$$

$$R_1 = 10 \text{ m}\Omega \quad V_1 = 415 \text{ V} \quad V_2 = 11 \text{ kV}$$

$$\text{Regulation} = 0.02 \text{ per unit}$$

$$\text{P.f} = 1 \quad \phi_2 = 0$$

$$I_1 = \frac{200 \times 10^3}{11,000} = 18.18 \text{ Amps}$$

$$0.02 = \frac{18.18 (R_e \times 1 + X_e \times 0)}{415}$$

$$R_e = R_1 + R_2 \left(\frac{V_1}{V_2} \right)^2$$

56)

$$0.02 = \frac{18.18 R_e}{415}$$

$$415 \times 0.02 = 8.3$$

$$\frac{8.3}{18.18} = R_e$$

$$R_e = 0.457 \text{ to } 3 \text{ dp}$$

$$R_e = 0.010 + R_e \left(\frac{415}{11000} \right)^2$$

$$0.457 - 0.010$$

$$\frac{0.447}{1.423 \times 10^{-3}} = R_z$$

$$R_z = 314.125 \Omega \text{ to } 3 \text{ dp}$$

$$\text{Max } R_z = 314.125 \Omega \text{ to } 3 \text{ dp}$$